

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date

**GENERAL INFORMATION** 

FAYC20210107020

Page 1 of 17

		FURMATION			
From	TTS	Client name:			
Contact:	Robin Huang	Contact:			
Tel/Fax:	0086-592-5219 260	Tel/Fax:			
E-mail	Inspection@tts-global.net	E-mail:	-		
Auditor(s)	Jack Zhu	Jack Zhu Cc: -			
Supplier:	Henan High-End Enterprise Co., Ltd.				
Factory name:	佛山市施博能铝制品有限公司 Foshan Splendid Aluminum Manufacturing Co., LTD				
Factory address:		广东省佛山市顺德区北滘镇高村工业区 13 号之六 No13-6,Gaocun industry, Beijiao town, Shunde district, Foshan city, Guangdong, China			
Contact.:		朱直军/JUM ZHU			
Audit type:	<b>Basic Factory Audit</b>	Audit Date			

**TTS's Disclaimer:**This report reflects our findings for the particular company in concern on the date of our service only. Any reader other that the party for which this report has been specifically issued is hereby informed that the General Conditions of Service of TTS contain liability limitation provisions.

	SEC.1	<ol> <li>Per the supplier (Henan High-End Enterprise Co., Ltd.) given information, the actual audited manufacturer was: Foshan Splendid Aluminum Manufacturing Co., LTD. It is a real manufacturer, main production range covers the foil containers, household aluminum foil, aluminum gas mat, decoration foil and other aluminum products.</li> <li>The factory did not provide the Bank account opening permit for reviewing during audit.</li> <li>The Management organization chart was provided by factory for reviewing when audit. And found the basic Management organization system was built.</li> <li>The factory provided the Import &amp; Export Trade License when audit, found it is valid.</li> </ol>
CONCLUSION	SEC.2	<ol> <li>The production processes without relevant operation instruction. Only provided Production flow chart for reviewing.</li> <li>Some of the production line was normal running when audit, but found the production machineries without relevant maintenance records.</li> </ol>
	SEC.3	<ol> <li>Found the quality control system was very easy. They check the quality when production the products, then reworking or pick out them directly when found the defects. (The final finish products inspection record, test records and the semi-finished inspection reports were available for reviewing. But they were very simply, such as a list, and not the inspection standard including)</li> <li>The factory claimed that they have 2 QC, but the identity of the QC was not found and confirmed on the audit site. They only inspected the goods when doing the assembly or packing process.</li> <li>No relevant QC/QA guide documents provided for reviewing during audit.</li> <li>Found the defective products did not mark/identify on-site.</li> </ol>


Basic Factory Au THIS DOCUMENT IS NON-NU		Report Number Report Date     FAYC20210107020       Page 2 of 17
	SEC.4	<ol> <li>The workshop environment is not very tidy, the material is placed in disorder also without enough identify, there is not basic regional division (packing/production/warehouse etc), and the workshop environment need improve for reaching the food contact level.</li> <li>The factory with the basic production machines/processes.</li> <li>Client specification:</li> </ol>
	SEC.5	I am looking at a factory to produce over 40,000,000 aluminum tins, and I want to make sure that this factory is a real factory and can produce 2 x 40HC per month without any issues. Reply: It is a small size manufacturer. Per the on-site observation, the factory maybe hard to reach the request production capacity. It need add the machines and workers.
OVERALL		The factory is small size manufacturer and with the basic production machines/ production ability. But the workshop layout/ the quality system need improve.

Auditor	Jack Zhu	Factory representative's signature:	-
---------	----------	-------------------------------------	---

# **Section 1: Company Overview**

	Factory Overview			
	1.1 Legal Validity			
★ Does the company have the valid business license?	🛛 Yes 🗌 No	★Business License Number:	9144060608452467 9C	
★ Year Established:	2013.12.03	★ Validity Period:	Long time	
★ Registered Address:		施博能铝制品有限公司 Bo aluminum products		
★ Company Address:		施博能铝制品有限公司 to aluminum products		
★ Annual review conducted by the Industrial & Commercial Bureau?	🛛 Yes 🗌 No	★Reviewed By:	Local government/顺 德区市场监督管理局	
★ Registered Capital:	RMB 10,000,000			
★ Corporate Representative:	朱直军 JUM ZHU			
★ Industry:	Produce/ Process/Selling: a products, plastic product			
★ Business Type:	Manufacturer	Trading Company	Combined	
★ Type of Ownership:	Private Owner Sino-foreign joint venture			
	State-owned Joir	nt venture		
★ Products Manufactured:	aluminum products, foil product	s, packing products etc	D	
★ Does the company have the Account opening permit?	Yes 🗌 No Remark: The	e factory did not provide	e it for checking.	

<b>Basic Factory Audit R</b> <i>This document is non-negotiab</i>		Report Num Report Date		20 Page 3 of 17	
★ The bank account	Bank:				
information on the Account opening permit?	Account	no.			
	710000111				
	Name:				
	Compar	ny name:			
	Etc				
★Does the Bank Account is a external account?	🗌 Yes	🛛 No Rer	nark: The factory did not prov	vide it for checking.	
★Does the information on Account opening permit is same as actual company status?	e Tes	Yes 🛛 No Remark: The factory did not provide it for checking.			
★ Does the company have the Tax Registration Certificate? And does it conform to factory's actual status?		☐ No Rer s license.	nark: The joining together o	f three certificates on the	
★ Does the company have the Organization Code Certificate? And does it conform to factory's actual status?		□ No Rer s license.	nark: The joining together o	f three certificates on the	
★ Does the company have	🛛 Yes	Yes 🛛 No			
the Import & Export Trade					
License? And does it conform to factory's actual status?	Remark	:			
	The fact	ory has it.			
1.2 Cor	npany Build	ing and empl	oyee Information-for factor	V	
		tification Type:		,	
Land Certification	Real Estate C		Lease Agreement	Factory Officer Claimed	
		al Building Size			
		nber of Buildin			
	★ Tota	al employee N	umber: <u>48</u>		
	1.3	Company N	lanagement system		
★1.3.1 Employee Headcount					
Department Name	Full Time En	nployee(s)	Part-Time Employee(s)	Total	
Chairman:	1			1	
GM:	1			1	
Production Dept.	25		4	29	
Technical Dept.	5		2	7	
Purchasing Dept.	4			4	
Admin. Dept.	2			2	
Trade Dept.	2			2	
QC Dept.	2			2	
★1.3.2 Management					
	Name		Education	Years in company	
Chairman:	-				
GM:	- 朱直军/ Jum	Zhu	Junior college	- 2013	
			Technical secondary	2013	
Production Dept. manger	刘俊/ Liu Jur	1	school graduate	2013	



### Comment:

- 1. Per the supplier (Henan High-End Enterprise Co., Ltd.) given information, the actual audited manufacturer was: Foshan Splendid Aluminum Manufacturing Co., LTD. It is a real manufacturer, main production range covers the foil containers, household aluminum foil, aluminum gas mat, decoration foil and other aluminum products.
- 2. The factory did not provide the Bank account opening permit for reviewing during audit.
- 3. The Management organization chart was provided by factory for reviewing when audit. And found the basic Management organization system was built.
- 4. The factory provided the Import & Export Trade License when audit, found it is valid.



Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date FAYC20210107020

Page 5 of 17

## Section 2: Production Capacity (factory)

	Prod	uction Capaci	ty		
	★ 2.1 Annual Produ	ction Capacity	y (Previou	ıs Year)	
	The factory did not pr	ovide them fo	or audito	r reviewing	
	★2.2 Pr	oduction Cap	acity		
★Product Name	★Production Lir	ne Capacity		★Actual Units P	roduced
Aluminum foil tray, cup	1000PCS/hour (Clair			00PCS/hour (claimed by factory, and near to auditor assess)	
aluminum foil			00Rolls/hour (claimed by factory, and near to auditor assess)		
Aluminum foil	1500PCS/hour (Claimed by factory) 120		200PCS/hour (claimed		
container/pan/	2.2 Dros	luction Machi	non	near to auditor a	assess)
★Machine Name	Z.3 Proc ★Brand & Model No.			per of Year(s) Used	★Condition
grinding machine 磨床	M7140	2	ANUIII	8	Normal
engine lathe 车床	CY-6150	2		8	Normal
milling machine 铣床	-	1		8	Normal
Drilling machines 钻床	3035	1		8	Normal
Air compressor 空压机	-	2		8	Normal
45T punching machine	J23L-45	5		8	Normal
30T scrap baling	-	1		4	Normal
presses		1		7	Norman
63T punching machine	-	1	1 5 Mair		Maintenance
Auto Feeder machine	WB/600	7		3-4	Normal
Foil rolling machine	-	3		4	Normal
Automatic shrinking machine	-	1		8	Normal
Sealing machine	-	1		8	Normal
Embossed machine	-	1		8	Normal
	★2.4 Pro	duction lines	audit		
	Cont	ent		Observations	/Comments
★2.4.1	Are the production lines audit?				
★2.4.2	Are the production proce operation instruction?			very easy	The process is
★2.4.3	Are the production mach maintenance records?	ineries with rel	evant	☐ Yes, ⊠ No	
	★2.5 Pro	ducts storage			
★Products	description/ style	Storage	e quantity	during audit on site	

<b>TTS</b> -Testing Technolog	y Service Ltd.		
<b>Basic Factory Audit Report</b> <i>THIS DOCUMENT IS NON-NEGOTIABLE</i>	Report Number Report Date	FAYC20210107020	Page 6 of 1

foil containers, household aluminum foil for Domestic sales

About 3-4 containers

17

Comment:

The production processes without relevant operation instruction. Only provided Production flow chart for reviewing.

Some of the production line was normal running when audit, but found the production machineries without relevant maintenance records.

# **Section 3: Quality Assurance(factory)**

		Quality Manage	ment System	and Pro	oduct Certification	
		3.1 Quality	Management	System	Certification	
□Certifi	cation	□Certifie	ed By	□C	ertificate No.	□Validity Period
			No ISO Ce	rtification	ו	
			3.2 Product C			
□Certifica <sup>®</sup>	tion	□Certified By	Certificate No		□Product Name & Model No.	□Validity Period
NIL		NIL	NIL		NIL	NIL
		3.3	Quality Contro	ol Mana	gement	
		Content			Observations	/Comments
★3.3.1 ★3.3.2	lines /pi 生产是有 Do the indeper	e quality control on all roduction process? 否有质量管控? QA/QC inspectors wo ndently from the prod 独立的 QA/QC?	ork	<ul> <li>Yes, all production lines/ production process have adequate quality control</li> <li>Yes, some production lines/ production process have adequate quality control</li> <li>No</li> <li>Remark: The quality control system was very easy, only Basic visual check.</li> <li>Yes</li> <li>No</li> <li>Remark: The factory claimed that they have 2 QC, but the identity of the QC was not found and confirmed on the audit site.</li> </ul>		
★3.3.3		any QA/QC inspector 一共多少人?	s in total?	2		
★3.3.4	(inspected) etc) w	relevant QC/QA guid tion method/ inspection ere available on site?	on standard	Yes No Remark: No documents provide.		
★3.3.5	availabl inspecti inspecti	relevant inspection r le on site (for final shi ion/ raw material incc ion/ semi-material ins	pment ming pection)?	⊠ Yes □ No Remar		imply.
★3.3.6	equipm And we	ne relevant test lab /T ents were available a ere the daily test repo itor review?	t factory?	☐ Yes ⊠ No Remar	s k: No documents pro	<i>v</i> ide.

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date FAYC20210107020

Page 7 of 17

### Comment:


Found the quality control system was very easy. They check the quality when production the products, then reworking or pick out them directly when found the defects. (The final finish products inspection record, test records and the semi-finished inspection reports were available for reviewing. But they were very simply, such as a list, and not the inspection standard including)

The factory claimed that they have 2 QC, but the identity of the QC was not found and confirmed on the audit site. They only inspected the goods when doing the assembly or packing process.

No relevant QC/QA guide documents provided for reviewing during audit.

Found the defective products did not mark/identify on-site.

# **Section 4: Production Flow (factory)**



The workshop environment is not very tidy, the material is placed in disorder also without enough identify, there is not basic regional division (packing/production/warehouse etc..), and the workshop environment need improve for reaching the food contact level.

The factory with the basic production machines/processes.

# **Section 5: Certification & Photos**

1-Certificate



**Document- inspection list** 

**Document- inline checking record** 

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date



FAYC20210107020

	3ª Bradenav : Water
海关进出口货物收发货人备案回执	2020-11月生产统可衣
	作品         产品         利利用         収益         111.00         产品         20.11         0.01         0.07.12         0.01.00 <th0.01.00< th=""> <th0.01.00< th="">         0.0</th0.01.00<></th0.01.00<>
	19 S323A-LID/AR107 0.073*326 22 552 224 22400 3.7 11 11 22 材料完成
企业名称 使山市施博能铝制品有限公司	201         S32286/ART08         0.104434         35         1085         290         28085/         8         13         17.5         30.5         材料形式成           21         S32286/ART08         0.104434         35         190         50         5000 √         1.4         3         4         7         材料形式成
统一社会信用代码	22         SS25A/MP1 74-4-TRM         0.1279472         100         370         60         3000         1.1         4         4         8         材料完成           23         SS25A         0.1279472         100         234         58         1900./         1         2         2         4         材料完成
海关编码 检验检疫音案号	24         S5254/ARI11         0.175#472         135         1822         134         6720,/         2.7         7.5         7.5         15         利用完成
位型位投資乗う 有效期 下期 水 和	25         S0050/11500         0.0824286         17         973         100         50060         6         .16.5         18.5         33         ННР.20.           26         S2050/115508/2         0.0824286         17         76         7         3915/         0.1         1.5         1.5         3         ННР.20.
(注册海关) 顺德海关	27         51908/765082         0.0594445         7.9         2522         249         284550         11.3         69         69         138         材料完成           28         52/38/76417         0.069287         8.7         4638         443         443625         21.6         147.5         141.5         239         材料完成
(注册用关)顺德进天 (注册百要) 2019年08月07日	29 #2073/12寸分格值 0.18+350 45 1674 278 278800 4.9 2.3 19.5 71.5 91 付料完成
	30         S181640接流杯         0.07%524         13.6         150         14         89900         3.1         3.5         7         10.5         材料完成           31         S181640接流杯/@1089         0.07%524         13.6         1992         140         85920         8         47.5         50.5         128         材料完成
注册备案专用章	32         S1308         0.044335         3.1         352         95         95759         8.1         19         24         43         MTF/SUR           33         S194A-11D         0.066229         2.2         380         63         120759         3.7         28         35.5         63.5         MH1%DR
	35         356         372.0         6.5         22.5         23.5         46         料料完成
	↓ ■ 2 県, 共 1 英
Desument everet information	Desument Production supertity as a l
Document- export information	
EE 1030 1313	1         7         7         7         7         7         7         7         7         9         900000         9         90000         900
電気 加速期 数1 上型 博用行使用把相對約約有效2010。1949	2月11日 - 2010日   次日田田山 - 田田日田山 - 10月253日   次日田田山 - 田田日田 - 10月14日   次日田山山 - 10月1日 - 日田日田 - 10月1日 - 日田日 - 日田田 - 日田日 - 日田田 - 日田日 - 日田日 - 日田日 - 日田日 - 日田 - 日田日 - 日田日 - 日田 - 日日 - 日 -
ARABANAN BERGEDULEST 4.0. SETTATION PER	<u>新聞</u> 二日前日前 二日 二日 二日 二日 二日 二日 二日 二日 二日 二日
····································	1795-18749 他 17153-1834 题 地址社 xxx 19971 1971 1 63 (444 11/1 600)
(前常 0.051431) 第2月4合 46 180,00 0 9 一出二(数単) (第2400 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	10 10:3-7:36 (465) 14:3
12-060/2000日 1200-0610 100000 0000000000000000000000000	197 10:10-11/231 (5.69 14) 年 18/8年 16 2014 2308 24 14 17 11/102 - 14:17 (5.99 14) 年 18/8年 18, 1027/1 11 25
	15-15-15 -16116 15359
	12 (1998
	8749
승규는         ····································	needing we de 20% excerces 7.11 200+00 = haiter
20. NO. 558	
20. NO. 558	
20. NO. 558	with the the test of t
20. NO. 558	(年代) (第2) (第2) (第2) (第2) (第2) (第2) (第2) (第2
GUL UL REI ER . HE SER	#デ 開設 超圧・強値時広 一般 12.31 単規: 単規: 単規: 単規:
Document- warehouse records	Document-production dept records
	DANSONS Gear
	田 地学研究 (2013)     国本     日本
	田 地学研究 (2013)     国本     日本
	田田 地球 (123)     国本     田田 (123)



# TTS-Testing Technology Service Ltd. Report Number Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE **Report Number** FAYC20210107020 **Report Date** Page 11 of 17 Office view Office view Samples room Samples room .... Samples room Samples room

# TTS-Testing Technology Service Ltd. Basic Factory Audit Report Report Number FAYC20210107020

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date





-----



Mould workshop

Mould workshop

# TTS-Testing Technology Service Ltd. Report Number

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE

**Report Number Report Date** 

### FAYC20210107020

Page 14 of 17



production workshop

production workshop

# TTS-Testing Technology Service Ltd. Report Number

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE Report Number Report Date

### FAYC20210107020

Page 15 of 17



production workshop

production workshop

# TTS-Testing Technology Service Ltd. Report Number

Basic Factory Audit Report THIS DOCUMENT IS NON-NEGOTIABLE

**Report Number Report Date** 

Page 16 of 17

FAYC20210107020



# <text><text><text><text>

Waste treatment room

Waste treatment room

\* \*

The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment. Version: REP-EE/HL-02