

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 1 of 59

A- GENERAL INFORMATION

From	TTS	Client name:	-			
Contact:	Robin Huang	Contact:	-			
Tel/Fax:	0086-592-5219 260	Tel/Fax:	-			
E-mail	Inspection@tts-global.net	E-mail:	-			
Inspector(s)	Frank Lee	Cc:	-			
Supplier	XXX	Product description	Chair			
Factory name:	XXX	-				
Inspection location:	AnJi, ZheJiang, China		1			
Item No.:	19031539,25089757 25089789,18965828 25089788,18808575 18992731,25089763 19031527,25089753 19031527,18902570 18934987					
PO No.:	W7207GL-BNE W7206GL-BNE W7197GL-SYD W7200GL-SYD W7278GL-SYD					
Inspection performed	Final Random Inspection	Inspection Date	XXX			
Approval by	Robin Huang- Dep	t. Manager				

B- INSPECTION RESULT SUMMARY

Checkpoint/ Result	PASSED	FAILED	PENDING	N/A	REMARK	
Quantity (section D)	X					
Conformity (section E)			X		Remark 1	
Workmanship (section F)			X		Remark 2	
Special Test (section G)			X		Remark 3	
Packaging (section H)			X		Remark 4	
OVERALL CONCLUSION (Client has the final decision to Reject or Approve)	Pending, due to remarks 1 -4					

Inspector's sign:	Frank Lee	Factory representative's sign:	On file
-------------------	-----------	--------------------------------	---------

C- REMARKS:

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 2 of 59

1.	For conformity check: For Item 25089788: No signed reference samples/color swatches were provided by client for compare when inspection. For other items: The signed reference samples were available at factory, and found the actual products were closed to signed samples. Please see enclosed photos for actual finding.
2.	For workmanship check:
	Please see section F-workmanship table for actual defects finding and confirm.
3.	For special tests
	For unit size and weight, please see section G-1 measure table for actual finding and confirm.
4.	For packing check:
	The packing information (shipping mark, packing method etc) were not given by client for reference, and found the actual products were matched to the shipping mark/ I.M printed information. Please see enclosed photos for actual

Note

1	For workmanship check, found the defects were within TTS advised AQL allowance, please see section F for actual
1.	Tor workinanship cheek, found the defects were writin TTB advised AQL anowance, please see section TTbr actual
	defects finding and final confirm.

2. 100% finished and packed.

finding and final confirm.

D-QUANTITY

P.O. No./ Brand	Item/Style/ Product No	Order Quantity	Shipment Quantity		Inspection Quantity	Units Packed in Cartons		Units Finished Not Packed		Units Finis	
	TIOduct NO	<u>Unit</u>	<u>Unit</u>	<u>Ctns</u>	Quantity	<u>Qty</u>	<u>%</u>	<u>Qty</u>	<u>%</u>	<u>Qty</u>	<u>%</u>
W7207GL- BNE	19031539	85	85	85	5	85	100	0	0	0	0
W7207GL- BNE	25089757	85	85	85	5	85	100	0	0	0	0
W7207GL- BNE	25089789	85	85	85	5	85	100	0	0	0	0
W7207GL- BNE	18965828	65	65	65	3	65	100	0	0	0	0
W7207GL- BNE	25089788	120	120	120	8	120	100	0	0	0	0
W7206GL- BNE	18808575	60	60	60	3	60	100	0	0	0	0
W7197GL-S YD	18992731	469	469	469	27	469	100	0	0	0	0
W7200GL-S YD	25089763	180	180	180	10	180	100	0	0	0	0
W7200GL-S YD	19031527	70	70	14	4	14	100	0	0	0	0
W7200GL-S YD	25089753	60	60	60	3	60	100	0	0	0	0
W7278GL-S YD	19031527	180	180	36	10	36	100	0	0	0	0
W7278GL-S YD	18902570	240	240	240	14	240	100	0	0	0	0
W7278GL-S YD	18934987	60	60	60	3	60	100	0	0	0	0

Inspection report				Inspection Number			HLMQ20210526005				
THIS DOCUMENT IS NON-NEGOTIABLE			R	Report Date		XXX			I	Page 3 of 5	59
Total:	===	1759	1759	1759	100	1559	100	0	0	0	0
List of CTN No.#	Total <u>100</u> Cart	Total 100 Cartons for sampling to inspection. Carton No.: N/A									
Result	Pass										

E-PRODUCT DESCRIPTION, STYLE, COLOR CONFORMITY

	CHECK POINTS	RESULT	COMMENTS
1	Against product information on PO	N/A	
2	Against product Specifications/Drawings/Photos	Pass	
3	Against submitted Samples/Color Swatch	Pending	Refer to remark 1
4.	Against instruction manual/ other information on packaging/ product.	Pass	

F-WORKMANSHIP

Inspection Standar	rd:		ANSI/ASQ Z1.4 (formerly known as MI	L-STD-105E	E)	
Inspection Level - Workmanship / Visual:			Fixed S/S	AQL - Critical Defectives: Not a			t allowed
Sampling Plan - W	Vorkmanship	o / Visual:	Single / Normal	AQL - Major Defecti	ves:		2.5
Sample Size – Wo	rkmanship /	Visual:	100sets	AQL - Minor Defecti	ives:		4.0
Item/ Color	S/S		Defective Descri	ption	Critical	Major	Minor
25089789	5	Wrinkle surface	ce		0	1	0
25089763	10	Wrinkle surface	ce		0	1	0
18902570	14	Scratch mark	Scratch mark				0
18902370	14	Uncut thread e	end		0	0	1
Other items	71	No defect four	nd		0	0	0
				Total Found:	0	3	1
				Accept:	0	-	-
				Result:		nding, see nd confirm 2)	

G-SPECIAL TEST

		CHECK POINTS		FINDINGS	RESULT	
1	1.	Description	Barcode scan test	No failure	Passed	
		Sample Size:	2pcs/item			



Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005	
	Report Date	XXX	Page 4 of 59

	Test method/ Ac	cepted Standard:	Scanned & correct.	
2.	Description	Carton drop test	No failure	Passed
	Sample Size:	1ctn/packing style	1	
	Test method/ Ac	cepted Standard:	61cm height/10times	
3.	Description	Unit dimension and weight	Please refer to G-1 table for actual finding and	Actual
	Sample Size:	1pc/item	- confirm (Remark 3)	finding
	Test method/ Ac	cepted Standard:	With rule and scale	
4.	Description	Static loading with 135kg	Found acceptable	Passed
	Sample Size:	1pc/item		
	Test method/ Ac	cepted Standard:	With one person on chair, and loading 135kgs for 1hr	
5.	Description	Stability test	Found acceptable	Passed
	Sample Size:	2pcs/item		
	Test method/ Ac	cepted Standard:	On a flat ground	
6.	Description	Impact test	Found acceptable	Passed
	Sample Size:	1pc/item	1	
	Test method/ Ac	cepted Standard:	On a flat ground, with 135kg, 25cm height drop	
7.	Description	Assemble and full function check	No failure	Passed
	Sample Size:	2pcs/item		
	Test method/ Ac	cepted Standard:	Assemble check with IM	
8.	Description	Base function check	Found acceptable	Passed
	Sample Size:	Full sample size		
	Test method/ Ac	cepted Standard:	Check the function	
9.	Description	Tape test on printing	No failure	Passed
	Sample Size:	1pc/item	1	
	Test method/ Ac	cepted Standard:	3M tape test for silkscreen printing	1
10.	Description	Smell test	No failure	Passed
	Sample Size:	Full sample size	1	
	Test method/ Ac	cepted Standard:	No bad odor found	1

G-1: Measurement

Item	Point	Product size(cm)	Product Weight(kg)
19031539	LXWXHX seat H	48x55x111-131cm Seat height:67-89cm Foot Sze:320mm	12.65kg
25089757	LXWXHX seat H	61x63x104-114cm Seat height:45-54cm Foot Sze:320mm	11.59kg



Т

....

ЪT

1.

Inspection report		Inspection report Inspection Number		HLMQ20210526005		
	ENT IS NON-NEGOTIABLE	Report Date	XXX	Page 5 of 59		
25089789	LXWXHX seat H	63x72x110-116cm		18.93kg		
		Seat height:51-58cm				
		Foot Sze:350mm				
18965828	LXWXHX seat H	37x49x60cm		5.19kg		
		Foot Sze:280mm				
25089788	LXWXHX seat H	57x61x83cm		6.81kg		
		Seat height:46cm				
18808575	LXWXHX seat H	64x67x115-124cm		16.12kg		
		Seat height:51-61cm		-		
		Foot Sze:350mm				
18992731	LXWXHX seat H	48x48x97-108cm		11.46kg		
		Seat height:47-59cm		-		
		Foot Sze:330mm				
25089763	LXWXHX seat H	50x53x101-112cm		11.01kg		
		Seat height:48-60cm		-		
		Foot Sze:320mm				
19031527	LXWXHX seat H	-		2.69kg		
25089753	LXWXHX seat H	52x60x88-99cm		9.12kg		
		Seat height:49-60cm		C		
		Foot Sze:320mm				
18902570	LXWXHX seat H	61x63x104-114cm		11.63kg		
		Seat height:45-54cm		c		
		Foot Sze:320mm				
18934987	LXWXHX seat H	50x57x99-111cm		10.62kg		
		Seat height:46-57		-		
		Foot Sze:320mm				

TH MO20210526005

T

H- PACKAGING:

1.Carton measure	1.Carton measurement									
		Size of case						of case (gs)		
Itom/Corton type	Quantity	SI	pec. $(\pm 5\%)$	6)		Actual		Spec.		Remark
Item/Carton type per case	per case	Length (cm)	Width (cm)	Height (cm)	Length (cm)	Width (cm)	Height (cm)	(± 10%)	Actual	Keinark
19031539	1	-	-	-	68	39	66	-	15.06	
25089757	1	-	-	-	62	29	60	-	13.37	
25089789	1	-	-	-	79	33	66	-	18.04	
18965828	1	-	-	-	53	21	51	-	6.29	
25089788	1	-	-	-	66	28	54	-	8.54	
18808575	1	-	-	-	77	39	66	-	18.04	
18992731	1	-	-	-	71	33	61	-	12.80	
25089763	1	-	-	-	73	38	62	-	13.19	
19031527	1	-	-	-	42	32	85	-	18.24	

Inspection report				nspection			IQ202105	26005		Page 6 of 59
THIS DOCUMENT IS NON-NEGOTIABLE			r	Report Da	te	XXX				rage 0 01 39
25089753	1	_	_		60	29	59		10.91	
18902570	1	_	_	-				_		
10,020,10	1	-	-	-	78	24	60	-	13.69	
18934987	1	-	-	-	66	33	60	-	12.55	
2.Assortment		•		•						
No. of Cartons Checked	No	. of Cartor Failed	ns	Findings / Comments				Result		
2cartons/iter	n	0	Not	No failure					Passed	
3.Packing method	l									
Seat, back rest and Gas lift, cover and Seat, back rest, bas nylon straps.	allen key pa	acked into	an inner b	oox. IM pa			export cart	ton seale	ed with t	ape and two
Result:	Pending,	due to rer	nark 4							

I- SAMPLE TAKEN :

NIL

PHOTOS



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 7 of 59



export carton 7.

carton packing view



Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005		
	Report Date	XXX	Page 8 of 59	



11. product view

12. **IM**





Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005		
	Report Date	XXX	Page 9 of 59	




19. compare to signed sample

20. compare to signed sample

	01			
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005		
	Report Date	XXX	Page 10 of 59	



Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005	
	Report Date	XXX	Page 11 of 59



31. export carton

32. export carton



e	0.		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 12 of 59





Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 13 of 59



43. product view

44. product view




Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 14 of 59





47. compare to signed sample

48. compare to signed sample



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 15 of 59




55. export carton

56. export carton

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 16 of 59



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 17 of 59



65. product view

66. product view





Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 18 of 59



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 19 of 59



The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment. Version: REP-EE/HL-02

80. export carton

79.

export carton

winc.com.au


<u> </u>			
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 20 of 59



85. product packing view

86. product view

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 21 of 59



87. product view

88. IM





Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 22 of 59



97. compare to signed sample

98. compare to signed sample



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 23 of 59



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 24 of 59



109. export carton

110. carton packing view



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 25 of 59



115. product view

116. product view



¥	÷ •		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 26 of 59



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 27 of 59






Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 28 of 59



129. product packing view

130. product view



131. product view

132. **IM**






Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 29 of 59




<u> </u>	<u> </u>		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 30 of 59



145. Seat height Measurement

146. Seat height Measurement

Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005	
	Report Date	XXX	Page 31 of 59



151. export carton

Qty:

Colour: Black

IURI

152. export carton

2303

U U	<u> </u>		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 32 of 59





Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 33 of 59



163. product view

164. product view



	<u> </u>		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 34 of 59



167. compare to signed sample

168. compare to signed sample



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 35 of 59




175. export carton

176. export carton


3YF

Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	HLMQ20210526005	
	Report Date	XXX	Page 36 of 59





Page 3/ 01 39	Inspection report	Inspection Number	HLMQ20210526005	
	THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 37 of 59



183. product view

184. **IM**



185. product view

186. product view



Inspection report	Inspection Number	HLMQ20210526005	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 38 of 59



193. compare to signed sample

194. compare to signed sample




Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 39 of 59





Ű,	01		
Inspection report	Inspection Number	er HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 40 of 59







Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 41 of 59



211. product view

212. product view



U U			
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 42 of 59









Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 43 of 59





Ű,	0.		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 44 of 59



<u> </u>			
Inspection report	Inspection report Inspection Number HLMQ20210526005		
THSPECTION TEPOTU THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 45 of 59



The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment. Version: REP-EE/HL-02

236. compare to signed sample

235. compare to signed sample

Ũ	0,		
Inspection report	Inspection Number	HLMQ20210526005	
THSPECTION TEPOTU THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 46 of 59



241. Seat height Measurement

242. Seat height Measurement

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 47 of 59



247. export carton

248. export carton

Inspection report	Inspection Number	HLMQ20210526005	
THSPECTION TEPOTU THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 48 of 59





<u> </u>	<u> </u>		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 49 of 59



259. compare to signed sample

260. compare to signed sample

e	0,		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 50 of 59



Inspection report	Inspection Number	HLMQ20210526005	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 51 of 59



 29. export carton
 270. export carton

 Exponentiation
 270. export carton

271. export carton

272. export carton



6	0.		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 52 of 59





Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 53 of 59



283. product view

284. product view



Ŭ	0.		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 54 of 59



289. Foot Measurement

4 .5

290. Foot Measurement

2 3 4 5

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 55 of 59



295. Color Fastness (rub) Test

296. Color Fastness (rub) Test

Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 56 of 59



¥	.		
Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 57 of 59



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 58 of 59



amb t 311. Defect-25089789 Wrinkle surface - major 312. Defect- 25089763 Wrinkle surface - major 313. Defect-18902570 Scratch mark - minor 314. Defect- 18902570 - Scratch mark - minor



Inspection report	Inspection Number	HLMQ20210526005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 59 of 59