

Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	SLMQ20210805005	
	Report Date	XXX	Page 1 of 37

A- GENERAL INFORMATION

From	TTS	Client Name:	-			
Contact:	Robin Huang	Contact:	-			
Tel/Fax:	0086-592-5219 260	Tel/Fax:	-			
E-mail	Inspection@tts-global.net	E-mail:	-			
Inspector(s)	Damon Yang	Cc:	-			
Supplier	XXX	Product Description	MEN HAT WITH WOVEN LABEL			
Factory Name:	XXX					
Inspection Location:	Zhangjiagang Province					
Item No.:	CA1344B/E					
PO No.:	21091					
Inspection Performed	Final Random Inspection	Inspection Date	XXX			
Approval By Robin Huang- Dept. Manager						

B- INSPECTION RESULT SUMMARY

Check Point / Result	PASSED	FAILED	PENDING	N/A	REMARK
Quantity (section D)	X				
Conformity (section E)			X		1
Workmanship (section F)	X				
Special Test (section G)			X		2
Packaging (section H)			X		3
OVERALL CONCLUSION (Client has the final decision to Reject or Approve)	Pending, due to remarks 1-3				

Inspector's sign:	Janon Kang	Factory representative's sign:	YANGZHIQIANG
-------------------	------------	--------------------------------	--------------

C- REMARKS:

Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 2 of 37


1. For conformity check

- 1.1 No approval samples/color swatches were provided by client for compare when inspection. Please see enclosed photos for actual product finding and confirm.
- 1.2 For Pantone check, the actual product color was similar to the request Panton, but not fully same, Please see enclosed photos for actual compare finding and confirm



2. For special tests:

- 2.1 For unit size and weight check, please see section G-1 measure table for actual finding and confirm.
- 2.2 Actual internal label size was 4x6cm instead of 4x5cm stated on SPEC, Please see enclosed photos for detail.
- 2.3 Actual symbol of recycle size on polybag was 2.8x3.2cm instead of 1x1cm stated on SPEC, Please see enclosed photos for detail.



6 6	~ v		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 3 of 37

- 3. For packing check:
 - 3.1 The actual Carton and inner box tape securing were not same as client given ref. photo, pls see below for detail.



Note

1. For quantity check: 100% finished and packed.

2. For workmanship check; found the defects were within TTS advised AQL allowance, please see section F-workmanship table for actual finding and confirm.

D- QUANTITY

P.O. No./ Brand	Item/Style/ Quantity		-	oment Inspection		Units Packed in Cartons		Units Finished Not Packed		Units Not Finished	
	Product No	<u>Unit</u>	<u>Unit</u>	<u>Ctns</u>	Quantity	<u>Qty</u>	<u>%</u>	<u>Qty</u>	<u>%</u>	<u>Qty</u>	<u>%</u>
21091	CA1344B	6228	6228	173	215	6228	100	0	0	0	0
	CA1344E	6228	6228		315	6228	100	0	0	0	0
Total:	===	12456	12456	173	315	12456	100	0	0	0	0

Inspection report		Inspection Number	SLMQ20210805005	
	IENT IS NON-NEGOTIABLE	Report Date	XXX	Page 4 of 37
			• 	
List of CTN No.#	Total <u>14</u> Cartons for sampling to 8,109,46,133,131,152,61,157,10	-		

E- PRODUCT DESCRIPTION, STYLE, COLOR CONFORMITY

	CHECK POINTS	RESULT	COMMENTS					
1	Against product information on PO	Passed	-					
2	Against product Specifications/Drawings/Photos	Pending	Refer to remark 1					
3	Against submitted Samples/Color Swatch	Pending	No approval samples provided for reference when inspection. (Remark 1)					
4.	Against instruction manual/ other information on packaging/ product.	Passed	-					

F- WORKMANSHIP

Result

Pass

Inspection Standa	rd:		ANSI/ASQ Z1.4 (formerly known as MII	L-STD-105E	<u>;)</u>	
Inspection Level - Workmanship / Visual:		Level II	AQL - Critical Defectives: Not		t allowed		
Sampling Plan - V	Vorkmansh	ip / Visual:	Single / Normal	AQL - Major Defecti	ves:		2.5
Sample Size – Wo	orkmanship	/ Visual:	315units	AQL - Minor Defecti	ves:		4.0
Item/ Color	S/S		Defective Descri	ption	Critical	Major	Minor
		Loose threads			0	1	0
		LOGO hung a	LOGO hung askew			1	0
	315	Uneven sewing (not symmetry)			0	6	0
CA 1244D/E		Thick yarn			0	1	0
CA1344B/E		Snagging			0	0	2
		The location of paper tag was wrong (on rear of product)			0	0	1
		Untrimmed th	read ends		0	0	11
				Total Found:	0	9	14
				Accept:	0	14	21
				Result:		Passed	

Note: A <u>Defective</u> is defined as a unit of product that contains one or more defects. A <u>Defect</u> is defined as any non-conformance of the inspected unit of product with specified requirements. A single defect is taken into account per each defective unit, in every case the most serious defect exhibited by the individual sample being inspected <u>regardless of the characteristic</u>.

G- SPECIAL TEST

	CHECK POINTS		FINDINGS	RESULT
1.	Description	Barcode scan test	No failure	Passed
	Sample Size:	8pcs		

TTS-Testing Technology Service Ltd. Inspection report Inspection Number

Inspection report	Inspection Number	SLMQ20210805005		
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 5 of 37	

	Test method/ Ac	cepted Standard:	Scanned & correct.	
2.	Description	Carton drop test	– No failure	Passed
	Sample Size:	1ctn		
	Test method/ Ac	cepted Standard:	61cm height/10times	-
3.	Description	Unit dimension and weight	Refer to table G-1 and remark 2 for actual finding	Pending
	Sample Size:	5pcs	and confirm	
	Test method/ Ac	cepted Standard:	With rule and scale	
4.	Description	Full function check	No failure	Passed
	Sample Size:	5pcs		
	Test method/ Ac	cepted Standard:	Wear on a model for fitting	-
5.	Description	Metal detection test	No failure	Passed
	Sample Size:	Full sample size	_	
	Test method/ Ac	cepted Standard:	No metal residue on products	-
6.	Description	Smell check	No failure	Passed
	Sample Size:	Full sample size	_	
	Test method/ Ac	cepted Standard:	Odorless	-
7.	Description	Color shade check	No failure	Passed
	Sample Size:	Full sample size		
	Test method/ Ac	cepted Standard:	No color differences	1
8.	Description	Rubbing test	No failure	Passed
	Sample Size:	8pcs		
	Test method/ Ac	cepted Standard:	No color transfer after test	1

G-1: Measurement

Point	Requirement	Sample 1	Sample 2	Sample 3	Sample 4	Sample 5	Unit
CA1344B LXH	N/A	20.5X22	20X22	20.5X22	20X22	20.5X22	cm
CA1344E LXH	N/A	20.5X22	20.5X22	20.5X22	20X22	20X22	cm

H- PACKAGING:

1.Carton measure	ement									
		Size of case					Weight of case (Kgs)			
Item/Carton type		Spec. (±5%)		Actual			Spec.		Domark	
		Length	Width	Height	Length	Width	Height	· · .	Actual	Remark
		(cm)	(cm)	(cm)	(cm)	(cm)	(cm)			

Inspection report					Inspection Number SLMQ20210805005		-)5005	D (() 27	
	THIS DOCUMENT IS NON-NEGOTIABLE			Report Da	te	XXX				Page 6 of 37
CA1344B/E Export	72	68	48	32	68	48	32.3	10	9.77	Spec form shipping mark
2.Assortment	2.Assortment									
No. of CartonsNo. of CartonsCheckedFailed		Findings / Comments				Result				
5cartons		0	N	No failure			Passed			
3.Packing method										
One pc per polybag,1pc per color box,12pcs color boxes (6pcs CA1344B+6pcs CA1344E) packed in a inner carton,then 72pcs(6inner cartons) packed in a export carton.										
Result:	Pending,	due to rer	nark 3							

I- SAMPLE TAKEN :

N/A

PHOTOS



8			
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 7 of 37



6 0			
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 8 of 37



Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 9 of 37



<u>_</u>	•		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 10 of 37



8 8	<i>, , , , , , , , , ,</i>		
Inspection report This document is non-negotiable	Inspection Number	SLMQ20210805005	
	Report Date	XXX	Page 11 of 37



The above reflects our findings at the time and place of inspection based on random selected samples in accordance with a previously agreed random statistical sampling standards. This report/certificate does not discharge or release sellers/suppliers from their commercial, legal or contractual obligations with regard to quality/quantity of delivery nor does it prejudice the buyer's right of claim toward sellers/suppliers for compensation for any found and/or hidden defects not detected during our random inspection or occurring thereafter. The report/certificate does not evidence shipment. Version: REP-EE/HL-02

32.

Symbol of recycle on polybag

31.

Rear of polybag

U U U	•		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 12 of 37



Inspection report Inspection Number SLMQ20210805005 Inspection Number SLMQ20210805005 Page 13 of 37




Inspection report Inspection Number SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLEReport DateXXXPage	Page 14 of 37



Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 15 of 37






U U	0,		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 16 of 37





6 0	/ J		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 18 of 37



U	//		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 19 of 37



Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 20 of 37



Inspection report Inspection Number SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLEReport DateXXX	Page 21 of 37




U	<i></i>		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 22 of 37




Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE Report Date	XXX	Page 23 of 37	
		14	



<u> </u>			
Inspection report	Inspection Number	SLMQ20210805005	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 24 of 37




Inspection report	Inspection Number	SLMQ20210805005	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 25 of 37



115. Polybag size check

116. Polybag size check


Inspection report	Inspection Number	SLMQ20210805005	
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 26 of 37



00	/ U		
Inspection report THIS DOCUMENT IS NON-NEGOTIABLE	Inspection Number	SLMQ20210805005	
	Report Date	XXX	Page 27 of 37



6			
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 28 of 37



Inspection report Inspection Number SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE Report Date XXX	Page 29 of 37



6 6	<i></i>		
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 30 of 37





141. Carton drop test

142. Carton drop test



143. Full function check

144. Full function check



Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 31 of 37



Inspection report THIS DOCUMENT IS NON-NEGOTIABLEInspection NumberSLMQ20210805005Report DateXXXPage 32 of 37	6 6			
E Report Date XXX Page 3/ 01 3/	Inspection report	Inspection Number	SLMQ20210805005	
	▲ ▲	Report Date	XXX	Page 32 of 37







Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 34 of 37



169. Uneven sewing(not symmetry)-Maj

170. Thick yarn-Maj

Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 35 of 37



8			
Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 36 of 37



S-Testing Technolo	gy Service Ltd.

Inspection report	Inspection Number	SLMQ20210805005	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 37 of 37

	Nil
183. Untrimmed thread ends-Min	184. Nil