Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 1 of 21

A- GENERAL INFORMATION

From	TTS	Client Name:	-	
Contact:	Robin Huang	Contact:	-	
Tel/Fax:	0086-592-5219 260	Tel/Fax:	-	
E-mail	Inspection@tts-global.net	E-mail:	-	
Inspector(s)	Loren Tan	Cc:	-	
Supplier	XXX	Loading Location:	Foshan Guangdong China	
Factory Name:	XXX	Loading Date	XXX	
Approval By:	al By: Robin Huang- Dept. Manager			

B- QUANTITY

PO No.:	Product Description	Item No.	Order QTY	Shipping QTY	Ctns/ Bags/ Pallets
	printer	-	1 pallets	1pallets	1 pallets
-	paper straw	-	10 cartons	14 cartons	14 cartons
	Safe Cabinet	-	180 cartons	132 cartons	132 cartons
TOTAL	-	-	191 cartons	147 cartons	147 cartons

C- OVERALL RESULT

RESULT	PASSED	FAILED	PENDING	ACTUAL FINDING	REMARK
OVERALL CONCLUSION			X		1~2
(Cliant has the final decision to Reject or Annrove)					

(Client has the final decision to Reject or Approve)

D- REMARK

1. For loading process:

Total loading 147cartons instead of 191cartons, Please see above quantity table for loading detail.

2. For Safe Cabinet inspection:

Actual found the product only has one drawer, instead of three drawers on the specification.

Actual found the cabinet door thickness was 8.5cm instead of 9cm on the spec.

Inspector draws 8pcs for workmanship and function check. 1pcs was found poor painting and rust inside the cabinet; 2pcs were found scratch mark on the cabinet surface. And All inspected samples were found poly-foam dust mark on the cabinet surface.

- 3. For printer and paper straw, inspector only checked the carton quantity.
- 4. The loading process is smooth under TTS inspector supervision.

E- GENERAL CONDITION CHECK:

GENERAL CONDITION	YES	NO	Reason:
Does the product conform to ref. Documents?	X		
Does Quantity conform to ref. documents?		X	See remark 1
Is the visual inspection for product satisfactory?	Х		

Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 2 of 21
Is storage condition satisfactory?	Х		See enclosed
			photos for detail
Is the product packing adequate?	Х		See enclosed
			photos for detail
Is the shipping container condition satisfactor	ry? X		See enclosed
			photos for detail

1. VISUAL INSPECTION DETAIL

Sample size: 8pcs for Safe Cabinet Inspection cartons: 8cartons for Safe Cabinet						
Item	Defective description	Critical	Major	Minor		
	Scratch mark on the cabinet surface	-	-	2		
Safe Cabinet	Poor painting and rust mark inside the cabinet	-	1	-		
Additional Ins	pection Check/Test.	Check/Test F	Result			
Quantity and assortment check on 1-3cartons/item		See photos for actu	al finding and conf	irm		

2. PACKING DETAIL

Item	Inner box size (LxWxH: cm)	Export carton size (LxWxH: cm)	Quantity per carton (unit)		
printer	-	-	1 sets		
paper straw	-	-	5000pcs		
Safe Cabinet	-	56x61x105cm	1pcs		
Packing Method:	See photos for actual finding				

3. LOADING DETAIL

Container No.	MAEU 8404599	Loading Quantity
Type of Container:	45'HQ	
Time of Container arrived:	1:30 PM	
Time of Loading started:	2:00 PM	See part B.
Time of Loading completed:	4:30 PM	
WHSE seal no.:	ML-CN4606003	

PACKING LIST

.

PHOTO ATTACHMENT

1 factory and warehouse

Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE

Report Number Report Date

Page 3 of 21

LSLL20201105001




1 export carton packing view (1)

2 export carton packing view (2)

Container Loading Supervision Report
THIS DOCUMENT IS NON-NEGOTIABLERepor
Report

Report Number Report Date LSLL20201105001



Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE

Report Number Report Date

LSLL20201105001 XXX



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 6 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 7 of 21




Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 8 of 21




31 product view (28)

32 product view (29)


Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 9 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 10 of 21




Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 11 of 21




Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 12 of 21




Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE	Report Number	LSLL20201105001	
	Report Date	XXX	Page 13 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 14 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 15 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 16 of 21



Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE


Report Number Report Date

LSLL20201105001 XXX

Page 17 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 18 of 21



11 loading container view (2)

12 loading container view (3)

Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE

Report Number Report Date

 LSLL20201105001

 XXX
 Page 19 of 21



Container Loading Supervision Report THIS DOCUMENT IS NON-NEGOTIABLE

Report Number Report Date

LSLL20201105001

Page 20 of 21



Container Loading Supervision Report	Report Number	LSLL20201105001	
THIS DOCUMENT IS NON-NEGOTIABLE	Report Date	XXX	Page 21 of 21

